Print on plain white paper - Part # 122919

INSTRUCTIONS

ELECTRICAL AND TUBING CONNECTIONS TO THE ASSISTANT'S CONSOLE FOR FIBER OPTICS

DANGER: Turn off all electrical power at the power source before making primary electrical connections.

WARNING: Turn off the air supply before making the tubing connections.



LEGEND

BK - BLACK
BL - -BLUE
BL/W - -BLUE/WHITE
BR - BROWN
GY - GRAY
GR - GREEN
OR - ORANGE
R - RED
V - VIOLET
W - WHITE
Y - YELLOW

NOTE: COLOR CODE MAY VARY DUE TO OPTIONAL CONFIGURATIONS.

Knight® by Midmark

Midmark Corporation • P O Box 286 • 60 Vista Drive
Versailles • Ohio • 45380-0286 • www.midmark.com
Phone: 937-526-3662 Fax: 937-526-5542